

TABLE OF CONTENTS

PREPERATION FOR OPERATION 1 -
ASSEMBLY WARNINGS 1 -
GENERAL WARNINGS 4 -
COMMENTS ON VERIFICATION 4 -
DISPLAY AND KEYBOARD 8 -
FIRST OPERATION9 -
WEIGHING THE PRODUCT9 -
WEIGHING BY PRICING9 -
REGISTERING THE UNIT PRICE LOOKUP
KEYS 10 -
USAGE OF EXTRA PRICE LOOKUPS (PLU) 10 -
WEIGHING WITH TARE 10 -
TOTAL MEMORY TRANSACTIONS 11 -
DISPLAY BACKLIGHT 13 -
RS232 INTERFACE 13 -
SETTINGS 13 -
1. TARE
2. ZERO SETTING: 14 -
3. TOTAL MEMORY, UNIT PRICE:
4. LIMITATION: 15 -
5. LCD / TIME SETTINGS: 15 -
6. POWER MANAGEMENT SETTINGS:
7. FILTERS: 15 -
8. CALIBRATION: 15 -
9. RELAY SETTINGS: 15 -
10. INTERFACE SETTINGS: 15 -
11. TESTING MENU: 16 -
12. Others: 16 -
THINGS TO DO BEFORE CALLING THE
SERVICE 16 -
TECHNICAL SPECIFICATIONS 18 -
LIST OF AUTHORIZED SERVICES 18 -

MKULMEB_EN-Rev.No:15 Rev.Date:25.01.2013

PREPERATION FOR OPERATION

After removing scale from its package, installation could be accomplished by following instructions given in "ASSEMBLY WARNINGS" part.

In models using post part, after setting the post to desired angle, screw the connecting screw to stabilize it.

Place the scale on a horizontal stable base. Avoid disturbing environmental conditions such as shocks, vibrations and air currents.

For setting the scale parallel to the base just turn the adjustable feet in order to stable the spirit level. (The bubble of the spirit level must be within the indicating circle)


Attach the adaptor to an electric outlet that has ground (220V), and connect it to adaptor input. There is an on/off key near the adaptor input. You can operate scale from this key.

NOTE: If scale has a rechargeable battery (sealed lead type), it should be charged at least 8 hour before first operation.

NOTE: There are protecting bands on the back display and post display. Taking out these bands make clear seeing the display. There may be white or blue band to protect stainless steel part of the scale. It should be taken off before using the scale.

ASSEMBLY WARNINGS

EGE-M AND EGE-LED HOLDING WIRE:



Attach the holding wire like above



EGE-M (ALKALINE BATTERY ATTACHMENT):

WARNING: WHILE D SIZE BATTERY IS ATTACHED, DO NOT CONNECT ADAPTOR!


If D size alkaline battery will be attached, unplug battery connector and remove rechargeable sealed lead type battery. Attach D size battery in right electrical poles. (See figure). Place (be careful to the direction) cover parallel to the base (See figure)

NOTE: D size battery cannot use on dual battery production

Remove adhesive tapes' protections before place the transparent cover



ASSEMBLY OF EGEB, MEB AND TEB SCALES:



Connect post to the bottom chassis with metric 10x25 imbus bolts.



Attach the shield with 10x25 hexagon bolts.



Attach indicator to the post like above. Do not remove after looked up. To remove indicator from post, remove two screws near the post connector.

Deci Deci	UYGUNLUK BEYANI Declaration of conformity	L C C Declar	UYGUNLUK BEYANI Declaration of conformity
H	Σ	TEN	
TÜM ELEKTRONİK MÜHENDİSLİK SAN. TİC. LTD. ŞTİ İSTANBUL DERİ ORGANİZE SANAYİ BÖLGESİ 1. YOL H7 ORHANLI 34956 TUZLA İSTANBUL / TURKEY	SLİK SAN. TİC. LTD. ŞTİ Esi 1. YOL H7 ORHANLI 34956 TUZLA URKEY	TÜM ELEKTRONİK MÜHENDİSLİK SAN. TİC. LTD. ŞTİ İSTANBUL DERİ ORGANİZE SANAYİ BÖLGESİ 1. YOL H7 ORHANLI 34966 TUZLA İSTANBUL / TURKEY	IK SAN. TIC. LTD. ŞTİ 1. YOL H7 ORHANLI 34956 TUZLA KEY
Otomatik Olmayan Tartı Aleti The non-automatic weighing instrument	Smf: Class: III	Otomatik Olmayan Tartı Aleti The non-automatic weighing instrument	Sunf. III Class:
Üretici Manufacturer	TÜM ELEKTRONİK MÜH. SAN. TİC. LTD. ŞTİ.	Üretici Manufacturer	TÜM ELEKTRONİK MÜH. SAN. TİC. LTD. STİ.
TiPi/MODEL1 Type/Model	EGE-M & EGELED	TiPiMODELi Type/Model	MEB & TEB
AB Tip Onay Sertifika numarası (uygulanabildiğinde): No of the EC type-approval certificate (where applicable):	ble): DK 0199.78	AB Tip Onay Sertifika numarası (uygulanabildiğinde): No of the EC type-approval certificate (where applicable):	DK 0199.77
AB Tip Onay Sertifikası'nda belirtilen üretim modeline, düzeltilmiş 2009/23/AT ve aşağıda belirtilen diğer yönetmeliklerin gereklerine uymaktadır. <i>corresponds to the production model described in the EC type-approval certificate and to the requirements of the Council Directive 2009/23/EC as amended and to the requirements of the following EC directives:</i>	e, düzeltilmiş 2009/23/AT ve aşağıda belirtilen SC type-approval certificate and to the mended and to the requirements of the	AB Tip Onay Sertifikası'nda belirtilen üretim modeline, düzeltilmiş 2009/23/AT ve aşağıda belirtilen diğer yönetmeliklerin gereklerine uymaktadır. corresponds to the production model described in the EC type-approval certificate and to the requirements of the Council Directive 2009/23/EC as amended and to the requirements of the following EC directives:	üzeltilmiş 2009/23/AT ve aşağıda belirtilen bype-approval certificate and to the nded and to the requirements of the
2004/108/AT Elektromanyetik Uyumluluk Yönetmeliği 2004/108/EC EMC directive	l'onetmeliği	2004/108/AT Elektromanyetik Uyumluluk Yönetmeliği 2004/108/EC EMC directive	etmeliĝi
Bu uygunluk beyam sadece bir onaylanmış kuruluş tarafından verilen Onay Sertifikası ile beraber geçerlidir. This declaration of conformity is only valid in conjunction with a certificate of conformity (Proof Of Conformity) of a Notified Body	afindan verilen Onay Sertifikası ile beraber tion with a certificate of conformity (Proof Of	Bu uygunluk beyanı sadece bir onaylanmış kuruluş tarafından verilen Onay Sertifikası ile beraber geçerlidir. This declaration of conformity is only valid in conjunction with a certificate of conformity (Proof Of Conformity) of a Notified Body	dan verilen Onay Sertifikası ile beraber with a certificate of conformity (Proof Of
Signature Juni Mal	TARIH 02.08-2010 Date	intza Signature Conton Mal	TARiH Date 02-08.2010

GENERAL WARNINGS

- In a failure case, behave according to the part "THINGS TO DO BEFORE CALLING TO SERVICE".
- Before cleaning, connection between scale and network must be cut off. Remove the plug to break of the electricity circuit before starting cleaning the scale. Then clean the scale with a dry or lightly detergent dampened cloth. Do not use solvents such as gasoline, benzene, thinner, alcohol and hard cleaning substances. Plug for electricity connection after being sure that the scale is completely dried.
- When it is necessary to transport, carry the scale (for removable plate scales) without its weighing plate to protect it from strokes. It will reduce the risk of being damaged to carry the scale with its original package and Styrofoam. Obey the transporting rules on package, during transportation.
- Do not place more product than scale's maximum capacity (maximum value written on data plate). Measurement component could be damaged.
- Attach the adaptor to an electric outlet that has ground. If you are not sure that outlet has ground, ask it to an electrician. Even if there is rechargeable sealed lead type battery in scale, use the scale with its adaptor as possible as you can.
- Place adaptor cable like it won't be damaged (somewhere no one would step on it, or nothing could crush to it) and place it like it won't move as it is possible.
- Do not pull the adaptor from its cable when you remove it from outlet or scale. Remove it from outlet with holding adaptor itself, and remove it from scale with holding the outlet on scale.
- Do not cover scale with nylon or any cloth like it. It must not touch anywhere except its legs.
- Weight, unit price and price displays should place as customer could see them easily in direct sales to public. If there is one display it should be placed as both customer and user could see it easily.
 - **NOTE:** Weighing instruments which got marking "Not to be used for direct sale to the public" should not use for direct sale to the public.
- In models with rechargeable battery, period of sealed lead type battery life can be change in large ranges according to usage of conditions. Periods explained in brochures are the longest periods of battery life

For instance, if a scale with LCD display Works for 8-10 hours in a day without using its display backlight. It can be used, without charging, for weeks. On the other hand if it can be used with display backlight it should be charged in every 2-3, even every day.

If you cancel a flashing point in a scale with LED display (in a scale with LCD display "- - - - - " is shown) and just use the weight display, battery life becomes shorter about 3-4 times.

- Battery should be replaced in every 2 years for models with sealed lead type rechargeable battery.
- Warranty does not applied to instrument that any of its security stickers or data plates were removed or damaged.

COMMENTS ON VERIFICATION

date

Do not take this section into consideration, if the weighing instrument does not bear "green M" sticker.

- Measuring instruments are reverified according to the legal requirements applicable in the individual Member States. See data plate for the year (near the CE marking) the measuring instrument is installed put into service. This and authoritative in two years but Period of circulation can be changed in your country. End of period of circulation you must go to relevant ministry with your machine.
 - If the instrument connected to additional equipment, the "red M" sticker will be affixed to the additional equipment, thus permitting it to be put into service and trade with the exception of direct sales to the public.
 - After the periodic or repairs, for inspection and sealing process authorized should take empty counter "Service Tag" from your services. Then, with this label should go to inspection and should be determined. Details about the inspection process can be found on the website from www.temterazi.com
 - Important stickers that permitting the instrument to be put into service and used in trade are;
 - Data plate with "green M" sticker
 - Security sticker(s) •


If modifications of any kind are made to stickers that given above after the weighing instrument being put into service, the competent Weights and Measures Authorities must be notified.

Detail Security of Seals:

The count of event counter is displayed during start-up for two seconds and is identified as C XXXX where XXXX is the count. This count must be the same with inscribed count of event counter on a label is placed near the data plate.

If this two numbers are not same, it means that the seal breaks down.

Weighing Scale;



Count of event counter that displayed during start-up

Event Counter




Event Counter Count of event counter that displayed during start-up

- The event counter is incremented each time the calibration or any metrological configuration 0 parameters are changed. The security of weighing instrument will be broken. In this case or any damage on event counter sticker or data plate, weighing instrument has verification done again. The responsibility of using weighing instrument with out verification belongs to user.
- NOTE: Calibration and Metrological configurations are secured with a special password. Therefore 0 these settings can not changed mistakenly. The increasing of event counter is an argument of consciously arrangement The responsibility of using weighing instrument in this situation belongs to user.

Places of Verification Stickers:

There must be a security sticker with TEM logo(Hologram) on data plate(Figure 3) 0



Data plate of weighing instrument

Indicators:


			Fun	Elektro	nik Mühe	ndislikS:	n.Tic.Lto	1.511.
BA	Tüm Elektronik Mühendislik Sanayi ve Ticaret Limited Şirketi		PLATFORM A:			PLATFORM B		
Model IVI	Serl No	08-92059		W1	W2		W1	W2
1008	-		Max	6 kg	15 kg	Max	60 kg	150 kg
СС ркрая.17	(III)		Min	40 0	100 9	Min	400 g	1000 g
	1 un		0=	2.9	5 0	0.0	20 g	50 g

Data Plate of weighing instrument with two load cell receptor Figure 3

• There must be a security sticker with TEM logo(Hologram) on Event Counter Sticker. On indicators the load cell serial number does not exists on Event Counter Sticker.



Weigh Instrument Event Counter Sticker



Indicator Event Counter Sticker

TEM	BAKIM SONRASI SAYAÇ ETİKETİ	
MÜHÜR OLM/ SÖK	ADAN GEÇERSİZDIR İMEYİNIZ	
Kalibras	yon Sayacı	$ \begin{array}{c} 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 2 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1$
Loadcell	model-seri n	

Service Event Counter

 In the weighing instrument, there must be an security sticker with TEM Logo(Hologram) to protect measurement components.

If there is platform connection to indicator;




Figure 5

Load cell connector bears the serial number(B) of weighing instrument on its identification label(A).
 These serial numbers must be same.



Figure 6

• Load receptor bears the serial number of the weighing instrument on its identification label.



• If junction box is used for load cell connections, there must be security sticker to prevent from any arrangement on it. This security sticker do not removed or damaged.


Data Plate:



Indikator Model Plate:

CE ⁰⁶ _{DK0199.77}	CE mark, the sign attached to the EC type approval certificate number and the last of two digits of the year.			
Μ	Green M has first verification's stciker			
Max	Largest capacity			
Min	Smallest capacity			
e =	Verification measure interval			

Platform İdentifier Sticker:



Platform: 70x80 LC model: 1263 LC maks: 635 KG Seri no: 21155468

Security Sticker:





TEM Logos Security Hologram

ŝ

Calibration Event Sticker

Service Event Counter



DISPLAY AND KEYBOARD

- **Zero Indicator** O: Shows that the weighing plate is empty. Before weighing a product, be sure that the weighing plate is empty and press "O " key for zero setting if the O indicator is off. Otherwise error may occur.
- **Equilibrium Indicator** D : Shows that the load on the weighing plate is well stabled. It is off while placing or removing the product. If D indicator goes off, the weight shown on the display may be wrong. Therefore, in order to read the weight, wait until D symbol appears after placing the product on the weighing plate.

<u>NET Indicator</u> NET: It is ON, when there is a tare. Actual weight value is NET weight value.

Tare Indicator : Shows that the tare effects the weighing. It flashes when the tare is not fixed. It is continuously on when the tare is fixed. (Only for scales with LCD display.)

- <u>Total Memory Indicator</u> **M**: It flashes when the total memory is containing a value. It remains continuously on while the content of the total memory is being displayed.
- <u>Battery Indicator</u>: R : Shows that the battery is used. If Battery indicator is ON, scale is powered by the battery. If it flashes, it is necessary to charge or change the battery in the shortest time.

Weighting instrument that designed with using LCD type display modules has four additional battery indicators for indicating the fullness of the battery and also they have a sliding battery charging animation mode, which is only activated when the adapter connection is established. While the adapter connection is not established, the battery frame around the battery indicators appears for indicating the battery is being used. Just before the battery becomes empty, the battery frame flashes.

- <u>W1 and W2 Indicator</u>: Shows actual weighing range (only for multiple range scales). See max, min, e values of each range on data plates.
- **Number Keys** : Used to enter unit price or other variables.
- **C** Key: Used for zero setting of unit price or other variables.
- T Key: Used for accepting the load as tare.
- O Key: Used for zero setting the scale when the weighing plate is empty.
- **<u>F</u> Key**: Used for reaching setting menu and some functions similar to settings.
- **<u>E</u> Key**: Used for adding to memory without weighing.
- A Key : Fixes the unit price.
- <u>**O**</u> **Key**: Used for taking printout. (Only for PC or printer options)
- W Key : Used for adding total memory.

M / X Key: Used for displaying and deleting total memory.

Key : Toggles backlight between ON, OFF, ON-OFF (only for LCD displays)

P Key: Used for reaching to price lookup table by a single key.

P1, P2... Keys : Used for reaching price lookup table by a single key.

U Key : Used for reaching to programs that are written bottom of the price lookup keys.

FIRST OPERATION

When scale is turn on all segments and symbols are seen. Numbers counting backwards are seen on display about 10 seconds. After that, maximum capacity and division is seen for a while and scale gets ready to weigh.

Value of zero is seen on display. \bigcirc and \triangleright indicators are ON. Nothing should be placed on weighing plate until it gets ready for weighing operation.

If there is any weight on weighing plate or there is no weighing plate on scale, ER 5 error message might be seen on display. Be sure that there is no weight on the weighing plate before calling service.

WEIGHING THE PRODUCT

Place the product on the weighing plate. Wait until the D indicator is on. Weight of the product is seen on display.

The value "O.OOO" should appear on the display and also the D and O indicator should be on when the weighing plate is empty. If the value on the display is not zero(or D indicator is not on), press O for zero setting. After establishing zero and balance, proceed to the weighing process.

WARNING: Absolutely not place any load more than maximum capacity of scale. ("Max" value on data plate) Product should be placed on weighing plate by hand. Leaving the product from high or throwing it on to the weighing plate (even the weight is low) scale may be damaged.

WEIGHING BY PRICING

If unit price is entered while weighing, price to pay is computed automatically. It is possible to enter unit price in 2 different ways.:

o "0", "1" ... "9" keys (number keys)

• **P1**,..., **P30**" price lookup keys.

Entered price should be seen on unit price display, price to pay should be seen on price to pay display.

Pres U (shift) key to reach the programs placed at the bottom (programs between P16-P30).

NOTE: Unit price can be entered as integer or fractional number.

Example: If 75.9 is wanted to see as unit price.

- 1) Press "7" key.
- 2) Press "5" key.
- 3) Press "." key.
- 4) Press "9" key.

NOTE: Unit price is cleared after product has been weighed. (When the weighing plate is empty). To prevent this, press "SABIT" key after entering unit price. To cancel automatic clearing of unit price continuously, turn OFF "Temporary Unit Price" (Set 3-2) specification from SEETINGS.

REGISTERING THE UNIT PRICE LOOKUP KEYS

Press one of **P1**,..., **P30** keys that you want to save the unit price, at least 3 seconds.

A long "Beep" signal is heard. Number of price lookup key you enter is seen on unit price display for a while.

Firstly press U key to reach the programs placed to the bottom (programs between P16-P30).

USAGE OF EXTRA PRICE LOOKUPS (PLU)

There are 250 price lookups. It is possible to reach first 30 programs directly by **P1**,...,**P30** keys. To reach other price lookup tables:

- o Press P key.
 - " PLU "is seen on price display.
- Enter program number. (For instance; press "7", "1" keys for registering the program number)

Unit price is saved in program 71 is seen on the unit price display.

First, "PLU 71" should be seen then price to pay should be seen on price display.

Registering the unit price on program keys:

• Enter price by using number keys.

This price is seen on unit price display.

• Press P key at least 3 seconds.

Flashing "PLU" is seen on price to pay display.

• Enter program number (for instance, press "7", "1" keys one by one for program numbered 71)

After 3 seconds long "Beep" signal is going to be heard. Saved program's number is seen on price to pay display for a while.

WEIGHING WITH TARE

- Place the tare weight on the weighing plate. Wait until the D indicator is on.
 Weight of tare can be read from weight display.
- \circ Press T key.

"dara" is seen on display for a second then value of "0.000" is seen on display.. **NET** indicator is ON. T symbol is flashing (only for LCD display). Tare has been weighted.

 \circ Place the product on weighing plate. Wait until \square indicator is on.

Product's net weight is seen on display screen.

o Make empty the weighing plate.

Wait until the D indicator is on. **NET** and T indicators are off. Tare is cancelled automatically.

Preset Tare:

- Tare value can be entered by using numerical keypad.
- o Press E key.

"E∟" message is seen on unit price display. Weight display is empty.

weigin display is

 \circ Press T key.

"EL" message is seen on unit price display.

Zero value is seen on Weight display. (for 30 kg 2x3000 zero value is "O.OOO")

• Weight value can be entered by using numerical keys "0","1",..."9".

If 1 kg Tare value will be set for 30 kg 2x3000 weighing instrument, "1.000" must be entered.

• Press F key to fix the tare value. In this case tare will not be cancelled when weighing plate is empty.

NOTE: Press T key 2 times for blocking the cancellation of tare. In this case, word "*Sabi t*" is seen on weight display for a while and tare symbol (only for scale with LCD display) begins to be continuously ON. To cancel tare, press T key when the weighing plate is empty.

Models with T symbol (for LCD display);

- Never ON : There is no tare
- FLASHING :When weighing plate is empty, tare will be cancelled automatically.
- Always ON :Tare is fixed. Press T key to cancel it when weighing plate is empty.

TOTAL MEMORY TRANSACTIONS

ATTENTION: If weighing instrument is **EGE-M** or **EGE-LED** and there is **no printer**, **not to be used** for Total Memory Transactions.

Total memory is used for adding weight and price of products to previous calculated weight and price. For this transaction there are two keys VV, MX on keyboard.

Adding to Total Memory:

• Place the product; to add to memory, on the weighing plate.

Wait until D indicator turns ON.

- Enter the unit price of product.
- Press VV key. Weight and price to pay are added to memory. Related **M** indicator flashes.

NOTE: During the zero, negatif and Full weight indications and also when the D indicator is off; adding to total memory will not be operated.

NOTE: After an adding to total memory transaction, new adding transactions will not be allowed until weighing plate is empty and "0.000" value is seen on weight display or new unit price value is entered.

ATTENTION: If weighing instrument is **EGE-M** or **EGE-LED** and there is **no printer**, **not to be used** for Total Memory Transactions.

NOTE: It is possible to see the total as soon as pressing VV key. For this transaction turns off "Adding without Showing Total" (Set3-1) specification from SETTINGS. In this case, total would be seen until the product is taken from weighing plate.

NOTE: Turn off "Temporary Unit Price" (Set3-2) specification from SETTINGS part to cancel zero setting of unit price continuously.

NOTE: Maximum 80 record is allowed for total memory transaction.

Adding Price to Memory without Weight:

If a product that has no relation between its unit price and weight (ex: bread) is required to be added to the total memory:

o Press E key.

"EL" message is seen on unit price display.

Weight display is empty.

• Enter the price you want to add by using number keys.

Price you entered is seen on price to pay display.

• Press VV key. Number seen on price to pay display is added to total memory. Total weight does not change.

Seeing and Erasing Total:

 \circ Press M X key.

Total weight is seen on weight display, price is seen on price to pay display, "TPA" and the number of products added to memory is seen on unit price display.

• Press $M \times K$ key to delete the total memory or press **F** to return to normal weighing mode.

Total indicator is seen as " M ".						
If total indicator is;						
off memory is empty.						
flashing memory has value.						
on memory value is seen.						

NOTE: It is possible to see the details of weighted products that are saved to total memory by pressing VV key. Detailed explanation can be found in "Seeing the Memory in Details" part.

ATTENTION: If weighing instrument is **EGE-M** or **EGE-LED** and there is **no printer**, **not to be used** for Total Memory Transactions.

Seeing the Memory in Details:

0	Press M	X key.
		Total weight is seen on weight display, price is seen on price to pay display, "TPA" and the number of products added to total memory is seen on unit price display.
0	Press VV	key.
		Weight and price that are saved first are seen on weight and price to pay display, "TPA" message is seen on unit price display.
0	When VV	key is pressed transactions are seen on display, respectively.
0	Press M	X key.
		Total weight is seen on weight display, price is seen on price to pay display, "TPA" and the number of products added to total memory is seen on unit price display.
0	Press M	\times key to erase memory or press F to return without erasing.

DISPLAY BACKLIGHT

Press 🔅 key to toggle between backlight ON, OFF and ON_OFF modes. To change backlight mode :

 Press key.
 For a second, backlight's mode is seen on display. DL On : Backlight ON *Backlight is continuously ON.* DL OFF : Backlight OFF. *Backlight is continuously OFF.* DLONFF : Backlight ON_OFF.
 Backlight is ON while weighing or pressing a key. Backlight is OFF when there is no weight on the weighing plate.

When scale is turned on, backlight mode is OFF.

If there will be a flashing point on display instead of weight value, backlight will be turned off automatically.

RS232 INTERFACE

RS232 connection and related settings for wieghing instrument with RS232 output are exists in PCdemohelp_tr.pdf in PCDemo folder in CD which is given with weighing insturment.

NOTE: F key is use to send data to computer which is EGE series

SETTINGS

• Pres F key during 3 seconds to enter settings menu.

"Set" and "Basis Menu Number" is seen on Weight display, and "Sub Menu Number" is seen on Unit Price display. Value is seen on Price to Pay display.

- Press F key to pass to following menu.
- Press O key to pass to following sub menu.

To change the type of On/Off values:

• Press T key.

To change the type of number values:

- Number keys should be used to change
- Press F key to save the number.
- Press F key for 3 seconds to return normal weighing.

EXAMPLE: Turn off "Set 2-4" to block Automatic Zero Setting specification continuously. (2:basis menu number, 4:sub menu number):

Press F key during 3 seconds.

"Set 1" is seen on Weight display, 1 (submenu number) is seen on Unit Price display. Value is seen on Price to Pay display.

Press F key once. Pass to menu 2. (Zero setting)

"Set 2" is seen on Weight display, 1 (sub menu number) is seen on Unit Price display. Value is seen on Price to Pay display.

Press O key 3 times. Pass to sub menu 4. (Automatic Zero setting)

"Set 2" is seen on Weight display, "4" (sub menu number) is seen on Unit Price display. Value is seen on Price to Pay display.

Press T key to make "Off" the value seen on Price to Pay display.

"Set 2" is seen on Weight display, "4" (sub menu number) is seen on Unit Price display. "Off" is seen on Price to Pay display.

Press F key 3 seconds to return normal weighing.

Turn off the scale and turn it on again.

SETTINGS MENU:

(Values in parenthesis are factory settings.)

1. Tare

1.1 Tare depends on stable equilibrium

(On)

(Off)

(If it is approved, its default value is ON and it cannot be changed)

1.2 Cancel tare operation in negative net value (On)

Smaller tare than valid tare. (In negative net value)

(If it is approved, its default value is ON and it cannot be changed)

1.3 Taring via Interface

Not in this type.

2. Zero setting:

2.1 Initial zero setting range control ±10% (On)

(If it is approved, its default value is ON and it cannot be changed)

2.2 Zero setting key range control < 2% (On)

(If it is approved, its default value is ON and it cannot be changed)

2.3 Zero setting depends on stability (On)

(If it is approved, its default value is ON and it cannot be changed)

2.4 Automatic zero setting (On)

If the weight indication is negative for more than 5 seconds when the equilibrium indicator is on, zero will be set automatically.

2.5 Automatic zero tracking (On)

If it is ON : Automatic zero tracking is done when the display is zero and stable.

If it is OF: Automatic zero tracking will not be done.

NOTE : If there is tare, automatic zero tracking program is not going to run.

2.6 Zero setting via interface (Off)

Not in this type.

2.7 Silo Mode Acitve/Passive (Off)

If it is ON :Silo Mode is enabled and initial zero setting control is not done.

If it is OFF :Silo Mode is disabled.

3. Total Memory, Unit Price:

3.1 Adding without showing total memory

(On)

If it is ON: Total cannot be seen after M+. Weighing is seen.

If it is OFF: Total can be seen until the weighing plate is empty, after M+

3.2 Temporary unit price (On)

If it is ON: Unit price is cancelled automatically when the weighing plate is empty.

If it is OFF: Unit price is not cancelled automatically when the weighing plate is empty.

3.3 Adding by M+ is depends on stability

(On)

(If it is approved, its default value is ON and it cannot be changed.)

minute

5. LCD / Time Settings:

- 5.1 LCD contrast (7) Can be adjusted between 1 and 9.
- 5.2 Backlight brightness (7)

Can be adjusted between 1 and 9

5.3 Date (Optional)

First two digits: day

Middle two digits: month Loot two diaito:

Last two digits:		year
5.4 Time		(Optional)
First two digits:	hour	

Last two digits:

6. Power management settings:

6.1 Empty weighing plate special display (On)

If it is ON: there will be a flashing point on display instead of weight value if scale is powered by battery and empty during 30 seconds. (in a scale with LCD display "- - - - - " is shown)

If it is OFF: does not work.

6.2 Empty weighing plate special display (On)

Manages Empty Weighing Plate Special Display mode and other power management modes.

If it is ON: Power management is done for all modes.

If it is OFF: No power management is done and "-- - - - " is not shown also.

7. Filters:

7.1 Median Filter

(It cannot be changed, if it is approved. Some models do not have the function.)

(5)

Minimum value is 1, maximum value is 9. If different value is entered, all filters run with default values.

7.2 Average Length (50)

(It cannot be changed, if it is approved. Some models do not have the function.)

Minimum value is 10, maximum value is 50. If different value is entered, all filters run with default values.

7.3 Minimum Average Length (1)

(It cannot be changed, if it is approved. Some models do not have the function.)

Minimum value is 1, maximum value is 25. If different value is entered, all filters run with default values.

7.4 Filter Break Count Value

(It cannot be changed, if it is approved. Some models do not have the function.)

Minimum value is 70, maximum value is 2800. If different value is entered, all filters run with default values.

8. Calibration:

8.1 Calibration coefficient

(It can be changed, if the calibration key is ON)

8.2 Maximum capacity

(It can be changed, if the calibration key is ON)

8.3 Division

0: 3000 1:2 x 3000

2: 3 x 3000 (division can not be set if it is approved)

3: 6000 / 7500 (division can not be set if it is approved)

- 4: 12000 / 15000(division can not be set it is approved)
- **6:** 1500

(It can be changed, if the calibration key is ON.)

8.4 Load Cell Maximum Capacity

(It can be changed, if the calibration key is ON.)

8.5 Maximum capacity unit (1)

- 0: g
- 1: kg
- 2: ton

(It can not be changed, if it is approved)

8.6 Gravity value of place where instruments was calibrated

(9.8022)

(1)

(It can be changed, if the calibration key is ON)

8.7 Gravity value of where place instrument will be used

(9.8006)

(It can be changed, if the calibration key is ON)

8.8 Load Cell mV/V value

mv/V value of used Load Cell

9. Relay settings:

Not in this type.

10. Interface settings:

(Only for PRINTER/PC type scales.)

10.1 Communication ON/OFF (On)

If it is ON : RS232 communication is active.

If it is OFF: RS232 communication is inactive.

(It must be activated in only for printer/pc type scales; otherwise ER 8 message will be seen.)

10.2 ID Number

(8888)

For PC output this Number is Instrument ID that is transmitted to PC in every package except continuous transmitting is ON.

See details in related documents.

10.3 Continuous transmitting (Off)

If it is ON: Activates continuous data transfer from scale to computer.


If it is OFF: Communication is not continuously, communication is done when a request sends from computer.

10.4 PC data package selection (11111)

It determines data package will be transmitted to PC.

1: It will be transmitted.

X X X X X 0: It will not be transmitted.



NOTE: If it is approved, price detail, unit detail and tare always are transmitted.

For printer type models see related documents.

THINGS TO DO BEFORE CALLING THE SERVICE

FAILURE SIGNALS ER 1 : Turn off the scale and then turn on it again. If failure continues, call service. FR 2 : Wait for a while. Turn off the scale and then turn on it again. If failure still continues, call service. : Wait for a while. Sure weighing plate is empty and press O ER З key. If failure continues, turn off the scale and then turn on it again. If failure still continues, call service. ER 4 : Turn off the scale and then turn on it again. If failure continues, call service. FR 5 : Initial zero setting range control error. Weighing not allowed. Be sure the weighing plate is empty. (If the weighing plate is not on scale, put it on to the scale)Turn off the scale and turn it on again, when the weighing plate is empty. Call the service if this warning is active again, when the weighing plate is empty. ER 6 : Turn off the scale and turn on it again. If failure continues, call service. ER 7 : Turn off the scale and then turn on it again. If failure continues, call service.

10.5 Baudrate

(0)

It determines the baudrate of RS232 communication between weighing scale and PC.

- 0:9600
- 1: 19200
- 2: 38400
- 3: 57600
- 4: 115200

11. Testing Menu:

12. Others: 12.1 Approved

(On)

(On)

(It can be changed, if the calibration key is ON.) If it is turned ON, all settings depended on condition "APPROVED" returns to factory settings values.

Not in this type.

12.2 Starting delay (10sn)

(If it is approved, it cannot be changed)

12.3 Calibration Switch (Off)

If calibration switch is off, settings with related calibration swichs can not change. Password is required to change position of calibration switch. If calibration switch position is changed to ON from OFF by this operation, event counter increased by one.The verification of weighing insturment is broken.(Please look COMMENTS ON VERIFICATION.)

- FR : Interface communication error. Turn off the scale and then turn on it again. If scale is not 8 pc/printer type and error still continues, call the service. If scale is pc/printer type, change SET 10.1 to "On" and turn off the scale and turn on it again. If still continues call the service. : Turn off the scale and then turn on it again. If failure continues, call service. ER 9 FR 11 : Turn off the scale and then turn on it again. If failure continues, call service. ER 12 : Turn off the scale and then turn on it again. If failure continues, call service. ER 13 : For pc/printer type models, If alibi memory is full, this message will be shown. There will be no data transmission to the PC/Printer and new transaction will be blocked until alibi memory erased. Erase alibi memory, turn off the scale and then turn on it again. For Printer type models see related documents. ER 14 : Loadcell cable detection error. Check loadcell connector and cable. If the connector is unplugged, plug it again. If failure continues, turn off the scale and then turn on it again. If failure still continues, call service. : Wait for a while. If failure continues, turn off the scale and then turn on it again. If failure ER 15 still continues. call service. FR 16 : See "PrinterUserManualAnnex.doc". If failure continues. call service. Lo bAtt: The battery is empty. Scale does not work. It should be charged or changed as soon as possible.
- Ful I (on weight display): Weight is more than maximum capacity.
- Ful I (Price display): Price to pay is too long to shown on display.
- nnnnnn : Platform (load carrier) is not fitted, or when there is weight on the platform weighing instrument may be tried to open up. On the empty platform. (The platform is not installed, replace) If necessary, there was no load on the instrument a more open platform.

If load carrier has two platform, you make sure to empty on load carrier.

The platform was empty, If failure still continues, call service.

ACOUSTIC SIGNALS

<u>Short beep</u> : Any key pressed.

<u>Double short beep</u> : Indicates the pressed key has no use for the related function.

<u>Long beep</u> : Same frequency with short beep. Indicates second function of the pressed key was done.

<u>Short beep and long beep different frequency</u>: It indicates desired operation could not be operated. For example, pressing T key when D indicator is off.

<u>Regular short beep 10 seconds period</u>: When battery is low, scale signals in every ten seconds. However, battery indicator flashes. It means that the battery is going to be empty and weighing cannot be done after a while. Adaptor should be connected as soon as possible. If you continue weighing without adaptor it continues signaling. Press \mathbf{F} key to cancel signaling. Look at the red light on adapter to control if it works or not.

TECHNICAL SPECIFICATIONS

Adapter: 220-240 VAC, 50 Hz input,Weighing Instrument Electrical SpecificationsMetrological Specifications: Look at data plate on scale.Operating temperature range : -10 °C ~ +40 °C

MODEL	CLASS	MAXIMUM CAPACITY (kg)	MINIMUM CAPACITY (kg)	FEATURE
MEB, EGE-B	III, IIII	1 -999999	20 e (III) 10 e (IIII)	Price Computing
EGE- M,EGE- LED	III	0,15 – 30	50 e (II) 20 e (III)	Price Computing

LIST OF AUTHORIZED SERVICES

FACTORY AND HEADQUARTERS:

Istanbul Deri Organize Sanayi Bolgesi Kazlicesme cad. No:48 Orhanli 34956 TUZLA/ ISTANBUL

TEL: (216) 394 25 25 FAX: (216) 394 83 82

www.temscale.com

Note: For latest information about authorized services, call factory service.

7,5 V DC output, 10 W : 7.5 V DC, 6 W



Tuzla Deri Organize Sanayi Bölgesi 1.Yol H7 Parsel Orhanlı PK:39456 TUZLA / ISTANBUL TEL:+90 216 394 25 25 FAX:+90 216 394 83 82 www.temscale.com Tum@tumelektronik.com